

PC	XT		PC	AT	
	D25		D9		
In	8	Carrier detect	1		In
In	3	Received data	2		In
Out	2	Transmitted data	3		Out
Out	20	Data term ready	4		Out
	7	Signal ground	5		
In	6	Data set ready	6		In
Out	4	Request to send	7		Out
In	5	Clear to send	8		In
In	22	Ring indicator	9		In
	1	Protective ground	-		

PC	XT		PC	AT	
	D25		D9		
	1	Protective ground	-		
Out	2	Transmitted data	3		Out
In	3	Received data	2		In
Out	4	Request to send	7		Out
In	5	Clear to send	8		In
In	6	Data set ready	6		In
	7	Signal ground	5		
In	8	Carrier detect	1		In
Out	20	Data term ready	4		Out
In	22	Ring indicator	9		In